



AXIDRAW


Included plastic parts

(numbers refer to parts, not to bags)


#1: Base



#2:
X support
block



#3: X motor plate




#4: X idler pulley support plate




#5: X idler lower spacer
(2mm thick, 4mm hole)




#6: X idler upper spacer
(4mm thick, 4mm hole)



#7: Carriage
plate lower




#8: Carriage
plate upper



#9: X belt tensioner plate





#10: X belt anchor posts
(8mm long, 3mm hole)




#11: Carriage plate spacers
(15mm long, 3mm hole)



#12: X belt anchor post spacer
(4mm thick, 3mm hole)



#13: Y rail support blocks



#16: Spacer tool
(for setting protrusion of Y rails)



#17: Spanner
(M4 and M3 sizes)